



Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



WORK ORDER INFORMATION

Work Order Name: WO/80008KN0812/1
Work Order Type: Weatherization
Audit Name: 80008KN0812-AUDIT

CLIENT INFORMATION

Client Name: _____ **Address:** _____
Client ID: 80008KN0812
Alt. Client ID: KNOX

AGENCY INFORMATION

Agency: Knoxville/Knox County CAC
Address: P.O.Box 51650
Knoxville, TN 37950-1650
Agency Phone: (865) 244-3080
Fax: (865) 544-1647
Email Address: jason.estes@cachousing.org

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

•Single Family Dwelling
Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.
City
House built in 1960
An EPA Certified Firm/Renovator is required.

Measures

Measure 1 Mastic the Return Box

Components

Inspected

Comment Liquid white Mastic to be applied to entire inside of return to seal all seams. Use foam board around edges to fill in any voids and mastic. Seal front of return box where it meets return register with appropriate caulk. No changes allowed. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Mate	Mastic the Return Box Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 80008KN0812

Alt. Client ID: KNOX

Work Order (Bid Form)

Work Order Name: WO/80008KN0812/1

Report Run On: 5/8/2010

DOE Weatherization Assistant

Version 8.6.0

Page 2 of 5

Measure 2 Mastic/Insulate Supply Boot qty 8**Components****Inspected**

Comment Liquid white Mastic to be applied to entire inside of boot to seal all seams. Top of boot where it meets subfloor to be caulked with appropriate caulk. Boots to be insulated on outside of boot to R-6. This is best performed with 2-part close cell foam. N

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Unspecified	Mastic/Insulate Supply Boot (+)	Each	8	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	labor	Each	8	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total: <input type="text"/>		

Field Notes:**Measure 3 DWH Pipe Insulation****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total: <input type="text"/>		

Field Notes:

Client Name:

Client ID: 80008KN0812

Alt. Client ID: KNOX

Work Order (Bld Form)

Work Order Name: WO/80008KN0812/1

Report Run On: 5/8/2010

DOE Weatherization Assistant

Version 8.6.0

Page 3 of 5

Measure 4 DWH Tank Insulation**Components****Inspected****Comment** extend pressure relief pipe as needed☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 80008KN0812

Alt. Client ID: KNOX

Work Order (Bid Form)

Work Order Name: WO/80008KN0812/1

Report Run On: 5/8/2010

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 5

Measure 5 Fix Any Other Heating System Problem Components**Inspected****Comment**☐

Existing unit will not turn off by thermostat, repair problem and install new thermostat. Install thermostat. Must be equal to Honeywell's PRO 4000 Programmable Thermostat (must submit equivalent to Housing Director for approval) . Must educate client on operation of thermostat.

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Repair of Heating System	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 80008KN0812

Alt. Client ID: KNOX

Work Order (Bid Form)

Work Order Name: WO/80008KN0812/1

Report Run On: 5/8/2010

DOE Weatherization Assistant

Version 8.6.0

Page 5 of 5